

Resetting Oil Service Indicator

2017 Mercedes Benz Sprinter

1. Turn the key to the ON position
 - DO NOT start the vehicle
 - Wait for computer to setup
2. On the circular interface - left side of steering wheel
Press the LEFT MENU button to display MILEAGE (if not already displayed)
3. Push the ▲ UP button to display the SERVICE-WRENCH ICON
4. Hold down the 0 button - left of the tachometer - until you hear a beep
 - This could take ~ 15 - 30 seconds
5. Then press RIGHT MENU button - on the same circular interface
 - Until the screen below is displayed



6. Press the ▲ UP arrow until you see the SERVICE-WRENCH ICON again
7. Briefly press and release the 0 button again
 - COMPLETE SERVICE will be the highlighted choice
 - Leave that as the choice
8. Press the ▲ UP arrow until you see the display CONFIRM COMPLETE SERVICE & RESET 3S
9. Press and HOLD the 0 button for ~ 3 seconds to reset
10. It will then display SERVICE CONFIRMED
11. Checking the service interval display (via the UP arrow)
 - Should display 20,000 miles